## METHOD OF DETECTING WEAR ON A SUBSTRATE USING A FLUORESCENT INDICATOR

## **Abstract**

A method of detecting wear on a substrate including coating a composition that includes a fluorescent compound on the surface of a first substrate, exposing the coated surface to wear, exposing the coated surface to radiation capable of exciting the fluorescent compound, and detecting the presence or absence of fluorescence.